

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
	W6265 Central Ave	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5349 Oak St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5333 Oak St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5328 CEDAR ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5349 Maple St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5336 Maple St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6184 US-8	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6241 Central Ave	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5384 LINDEN ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5341 Cedar St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5332 Linden St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	Lot W2 Block 5-Corner of Linden St & Central Ave	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5375 Linden St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	Y	10/7/2024	visual insp at meter	
	N5323 Linden St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5319 Oak St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6265 CENTRAL AVE	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5378 Walnut St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5387 WALNUT ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6215 Central Ave	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5379 Walnut St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5334 Cedar St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5386 Walnut St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5335 LINDEN ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6178 US-8	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5383 LINDEN ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5394 Linden St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5340 Maple St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5335 Cedar St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6289 Central Ave	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5395 Walnut St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5398 Walnut St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5398 Walnut St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5399 WALNUT ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5399 WALNUT ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6218 Lawrence St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5335 LINDEN	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	611 1ST ST S Lot 11	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	611 1ST ST S Lot 15	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	611 1ST ST S Lot 19	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5328 CTY RD I	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5331 Co Rd I	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	Block 10- High School South	N	C	N	2"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	Block 10- High School Main	N	C	N	3"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	Block 10- High School North Building	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6217 LAWRENCE AVE	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	Lots 4,5,6, Block 15- Bus garage	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5346 CTY RD I Lot 3 Block 5	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5346 CTY RD I Lot 2 Block 6	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6164 Lawrence St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5321 Cedar St	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5317 LINDEN ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5318 LINDEN ST	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N5312 Chestnut	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	N4864 Co Rd I	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			
	W6217 Hwy 8	N	C	N	1"	10/01/1997	C	1"		SF						Installed after lead ban	N			Installation record	N			